

7901 N I-35, AUSTIN, TEXAS 78753 | 512.832.7000 | WWW.TXDOT.GOV

May 2, 2016

Edward G. Polasek, AICP Transportation Services Director City of Georgetown P.O. Box 409 Georgetown, Texas 78627-0409

Dear Mr. Polasek,

I am responding to your letter addressed to Susana Ceballos, received April 14, 2016, regarding the Austin Avenue Bridge Inspection Report.

These bridges pose a unique situation since they were built on-system but became off-system structures relatively recently. This means they were built to the Texas Department of Transportation's specifications. The most recent bridge inspector was under the impression that since this was the case, the bridges should be evaluated as on-system structures. However, that is not correct since TxDOT load rating policy clearly states they should be evaluated as off-system structures. As such, they are still required to be load posted, however; the most recent analysis supports raising the posting to 68,000 lbs. gross and 34,000 lbs. tandem axle.

TxDOT will order the new load posting signs and let you know when they are ready to be picked up. If you have any questions, please do not hesitate to contact me at (512) 832-7376 or at kathleen.newton@txdot.gov.

Sincerely,

- Docusigned by: Kathleen Deirohe Newton P.E.

-4C4DD77C10264B8...

Kathleen D. Newton, P.E., PMP Austin District Bridge Engineer

cc: Terry G. McCoy, P.E., Austin District Engineer, TxDOT

Bobby A. Ramthun, P.E., Georgetown Area Engineer, Austin District, TxDOT

David Morgan, Georgetown City Manager

Jim Briggs, Georgetown General Manager of Utilities

Nathanial Waggoner, Georgetown Transportation Analyst

David J. Lubitz, P.E., Aguirre & Fields, LP